CORRES. CONT	ROL
OUTCOING LTD	NO

UTGOING LTR. NO

	4700.1		
03-RF-00900			
DIST.		LTR	ENC
DIETER, T.			
FERRERA, D.W.			
FERRI, M.S.			
LINDSAY, D.			
LYLE, J.			
MARTINEZ, L. A.			
PARKER, A.			
POWERS, K.			
SHELTON, D.C.			
SPEARS, M.S.			
TRICE, K.D.			
TUOR, N. R.			



June 17, 2003

03-RF-00900

AGUILAR, P. ALBIN, C. AUBLE, M. BEAN, C. BUTLER, J. L CERCLA AR (T130G) DECK, C. FREIBOTH, C. GEIS, A. GIBBS, F. HUMISTON, T. KNAPP, S. LARSON, E MARSCHALL, J.R. MARTIN, D. MYERS, K. NESTA, S. NININGER, R. OLIVER, R. OMAN, K. PLAPPERT, R. PRIMROSE, A. ROSENMAN, A. SNYDER, D.P. THOMPSON, J. WIEMELT, K. WILLIAMS, L.

Mr. Darrell R. Dearborn Solid Waste Program Unit

Colorado Department of Public Health and the Environment

4300 Cherry Creek Drive South Denver, Colorado 80246-1530

Mr. Roy Laws

Jefferson County Department of Health and Environment

260 South Kipling Street

Lakewood, Colorado 80226

FINAL CLOSURE OF THE "NEW SANITARY LANDFILL" - TJH-002-03

Dear Sirs:

This is to notify your agency that in accordance with CDPHE regulations, 6 CCR 1007-2, Part 258, Section 3.5.8, the Rocky Flats Environmental Technology Site has completed final closure of the "new sanitary landfill," that was never used. The landfill cell was located in the northwest guadrant of the Site.

This letter is to certify that the closure activities were conducted consistent with the approved Closure Plan for the New Sanitary Landfill, dated October 9, 2002. The closure consisted of removing/recycling the tires that held the UV liner in place, removing the entire synthetic liner from the bottom edge of the cell to the top of the cell, and auguring the clay liners and filling them with sand to render them incapable of retaining water. Additionally, all structural material within three feet of the existing grade was removed, and pipelines below three feet were grouted to disrupt a flow path. The areas were subsequently backfilled with the dirt that had been bermed in the area and reseeded.

The Site will implement post-closure requirements of monitoring the area for subsidence, erosion, seeding quality, and ponding over the next two years.

If you have questions or require additional information, please contact Steve Nesta at (303) 966-6386.

AUTHORIZED CLASSIFIER

CORRES.CONTROL

TRAFFIC

PATS/130

CONFIDENTIAL SECRET

LICNI UNCLASSIFIED

ADMIN RECRD/T130G

SIGNATURE:

CLASSIFICATION

CJ FREIBOM 06/17/03

IN REPLY TO REP CC NO .:

ACTION ITEM STATUS: PARTIAL/OPEN CLOSED

ORIG. & TYPIST INITIALS:

Timothy J. Humiston, PE

Chief Engineer

Remediation, Industrial D&D, & Site Services

SMN:pvt

Sincerely

SMN:pvt

RF-46469(Rev.9/94)

Kaiser-Hill Company, L L C

A**DMIN RE**COR:

Rocky Flats Environmental Technology Site, 10808 Hwy. 93 Unit B, Golden, CO 80403-8200 ● 303-966-7000

BZ-A-000599 IA-A-001468